

## Casino Kitchen California

Loss Event: Microbial Growth

### CASE STUDY

After repeated use and dripping water, a pot wash area in the kitchen of a world-class luxurious gaming casino had long-term water damage. The water damage caused microbial growth that required remediation and repair.

BELFOR Property Restoration responded with four water damage specialists who performed the remediation project.

As with any microbial remediation project, the goal was to discreetly remediate and repair the damage in a safe and efficient way while allowing the casino to continue serving guests.

To prevent any business interruption, BELFOR technicians worked strategically at night and in sections so that the kitchen could remain operational at all times.



### 24/7 Emergency Number

**800-856-3333**

Corporate Headquarters:

185 Oakland Ave., Suite 150

Birmingham, MI 48009-3433

Toll Free: 888.421.4111

Direct : 248.594.1144 Fax : 248.594.1133

[www.belfor.com](http://www.belfor.com)

### Commercial Services ▶

Reconstruction Services | Smoke & Soot Removal | Water Extraction | Mold Remediation  
Structural Dehumidification | Structural Cleaning & Decontamination | Corrosion Control  
Air Duct Cleaning | Deodorization | Contents Restoration | Document & Media Recovery  
Machinery & Equipment Decontamination, Rebuilding & Repair | Environmental Services

### Residential Services ▶

Reconstruction Services | Smoke & Soot Removal | Water Extraction | Mold Remediation  
Structural Dehumidification | Structural Cleaning & Decontamination | Air Duct Cleaning  
Deodorization | Contents Restoration | Document & Media Recovery | Environmental Services