

CASE STUDY

NEW MILFORD HIGH SCHOOL New Milford, Connecticut

When the roof of New Milford High School caught on fire, approximately 150,000 square feet of the building suffered heavy smoke and water damage. This included classrooms and the mechanical room throughout the building.

Within weeks, school was scheduled to begin. School and city officials were convinced at the time of the loss that the only way to start school on time was to order temporary classrooms at a cost of several million dollars.

BELFOR SAVES THE DAY

BELFOR Connecticut was contacted and made a firm commitment to have the school open on time. Plans for temporary classrooms were canceled.

BELFOR Connecticut immediately mobilized more than 200 people of all trades working multiple shifts. Collaborative assistance was provided by BELFOR Long Island and BELFOR Westchester offices.

The scope included:

- Complete removal and replacement of all ceiling tiles, ceiling grid, drywall, finishes, casework, lockers, flooring, debris removal and cleaning.
- Complete content removal, cleaning and re-installation.

The project was completed in 60 days - "on time" - after extensive repairs, allowing school to begin in the Fall semester.



INDUSTRY:

K-12 Education

SERVICE:

Fire and Water Damage Restoration, Reconstruction



CHALLENGE



Schedule - Extensive repairs to the school had to be completed within 60 days so that classes could resume for the fall semester.